

Mobile No. 9779079704

Lt Col G S Jeryal, Retd
Ex-President GHS-79
Flat No. 704/E-3 Block
GHS-79, Sandeep Vihar (AWHO)
Sector-20, Panchkula

No. GSJ/32/2019

Date : 16th May 2019

The Fire Station Officer
Sector-5,
Panchkula (Haryana)


Reg: Non-functioning of Fire Fighting System in GHS-79 Sector-20, Panchkula

Sir,

1. It is brought to your kind notice that Fire Fighting system of our Society viz GHS-79, Sector-20, Panchkula has not been properly functional for the last two years. In spite of pointing out this lapse a number of times to the President Col R S Rathee in various forums like GBMs/AGMs etc., no adequate action has been taken except placing a few fire extinguishers here and there in the blocks some of which have gone over-dated/ not filled timely. This willful inaction on the part of President, has put the life of all the 556 resident families of our housing complex into grave danger.

2. You are, therefore, kindly requested to visit our Society Complex (comprising of stilt+4 storey and stilt+7 storey buildings) and after checking all necessary fire-fighting equipment/fixtures, advise the Society Management accordingly keeping in view the relevant provisions/guidelines as laid down in Haryana Fire Service Act 2009 which stipulates its strict compliance in the Housing Complex having multi-storey buildings with height of more than 15 metres.

Thanking you,


(Lt Col G S Jeryal, Retd)

Copy to :

The Director General
Haryana Urban Local Bodies-cum-Fire Services Deptt
Bay No. 11-14, Sector-4
Panchkula (Haryana)